DESKLINE Control Boxes CBD4 & CBD6S

Error Codes



Error codes for CBD4 troubleshooting:

Error States	Name	Description	Potential Cause	Action
E08	Watchdog	Indicates that software failed to activate routine that checks calculations	Program fault Processor problems	Contact LINAK A/S
E09	Stack overflow	Indicates that software caused a stack overflow (infinite loop)	Program fault Processor problems	Contact LINAK A/S
E10	Short circuit	One of the motor outputs are short circuited	Squeezed motor cable Short in motor	Exchange cable or motor
E11	Double key pressed	Indicates that one or more key (s) are pressed on passive matrix – error on a control	Multiple keys pressed on 2 different handsets or squeezed control cable button constalling activated	
E12	Cable orientation	One motor cable is not mounted correctly	Motor cable plugged upside down Bad cable	
E13	Position error	One channel has position different then others	Too much back drive occurred	
E14	Power fail	Power fail happened	Mains missing	
E15	Channel mismatch	Change in number of actuators since initialization	Disconnection DL added	

E17	Channel 1	Channel 1 is	Disconnection	
L1/	missing	detected missing	DISCOMMECTION	
E18	Channel 2	Channel 2 is	Disconnection	
	missing	detected missing		
E19	Channels 3	Channel 3 is	Disconnection	
	missing	detected missing		
E20	Channel 1 type	Channel1 is not same	Change in DL type	
	error	type as when		
		initialized		
E21	Channel 2 type	Channel 2 is not	Change in DL type	If DL is not
	error	same type as when		changed –
		initialized or not		failure in leg
		same type as channel		
F22		1		. D.
E22	Channel 3 type	Channel 3 is not		Change in DL
	error	same type as when initialized or not		type
		same type as channel		
		1		
E23	Channel 4 type	Channel 4 is not	Change in DL type	
223	error	same type as when	andinge in 22 type	
		initialized or not		
		same type as channel		
		1		
E24	Channel 1 pulse	Channel 1 had too	Loose/faulty cable	Check cable
	fail	many pulse errors	Hall sensor PCB	connections
				change cable
E25	Channel 2 pulse	Channel 2 had too	Loose/faulty cable	
506	fail	many pulse errors	Hall sensor PCB	
E26	Channel 3 pulse	Channel 3 had too	Loose/faulty cable	
E27	fail	many pulse errors	Hall sensor PCB	
EZ/	Channel 4 pulse	Channel 4 had too	Loose/faulty cable Hall sensor PCB	
E28	Channel 1	many pulse errors Overload up	Reached end stop	
LZO	overload up	occurred on channel	Reactied end stop	
	Overload up	1		
E29	Channel 2	Overload up	Reached end stop	
223	overload up	occurred on channel	Hit obstruction	
		2		
E30	Channel 3	Overload up	Reached end stop	
	overload up	occurred on channel	Hit obstruction	
		3		
E31	Channel 4	Overload up	Reached end stop	
	overload up	occurred on channel	Hit obstruction	
		4		
E32	Channel 1	Overload down	Reached end stop	
	overload down	occurred on channel	Hit obstruction	
		2		

E33	Channel 2	Overload down	Reached end stop	
L33	overload down	occurred on channel	Hit obstruction	
	overroud down	2	The observeron	
E34	Channel 3	Overload down	Reached end stop	
	overload down	occurred on channel	Hit obstruction '	
		3		
E35	Channel 4	Overload down	Reached end stop	
l	overload down	occurred on channel	Hit obstruction	
		4		
E36	Channel 1 anti	Anti collision	Hit obstruction	
	collision	triggered on channel		
E37	Channel 2 anti	Anti collision	11:4 - b - 4	
E3/	collision	triggered on channel	Hit obstruction	
	Collision	2		
E38	Channel 3 anti	Anti collision	Hit obstruction	
	collision	triggered on channel		
		3		
E39	Channel 4 anti	Anti collision	Hit obstruction	
	collision	triggered on channel		
		4		
E 40	Channel 1 SLS	Safety limit switch	Hit obstruction/hall	
		activated on channel	failure	
		1		
E41	Channel 2 SLS	Safety limit switch	Hit obstruction/hall	
		activated on channel	failure	
E42	Channel 3 SLS	2 Safety limit switch	Hit obstruction/hall	
L4Z	Charmer 3 3L3	activated on channel	failure	
		3	lalidic	
E43	Channel 4 SLS	Safety limit switch	Hit obstruction/hall	
		activated on channel	failure	
		4		
E44	Channel 1	Pulses counted	Motor poles are	
	direction	wrong direction in	crossed	
		channel 1	Hall sensor cables	
			are crossed	
E45	Channel 2	Pulses counted	Motor poles are	
	direction	wrong direction in	crossed	
		channel 2	Hall sensor cables	
E46	Channel 3	Pulses counted	are crossed	
E40	direction	wrong direction in	Motor poles are crossed	
	direction	channel 3	Hall sensor cables	
		Charlier 5	are crossed	
E47	Channel 4	Pulses counted	Motor poles are	
	direction	wrong direction in	crossed	
		channel 4	Hall sensor cables	
			are crossed	

Error codes for CBD6S troubleshooting:

Error code	Name	Description
8	Unexpected Reset	Unexpected reset caused by a software error or external reset
9	LIN error	An error occur on LIN bus
10	Power fail	Power fail occurred or power regulator adjusted below 10%
11	Channel count changed	Number of channels connected to system has changed since last initialisation
12	Position difference	Difference between minimum and maximum position of a reference has been exceeded
13	Short circuit	Short circuit has been detected while running
14	Checksum	Position checksum check failed, all channels has position lost
15	Power limit	System has reached its power limitation
16	Key error	Illegal key combination or change of keys
17	No Safety	Safety function has not allowed movement but input active
18	Missing initialisation plug	A special service tool is required to change number of channels to the system
23	Channel 1 missing	Actuator is missing
24	Channel 2 missing	7
25	Channel 3 missing	
26	Channel 4 missing	
27	Channel 5 missing	7
28	Channel 6 missing	
29	Channel 1 type	Actuator type has changed since initialisation, or detected wrong.
30	Channel 2 type	Actuator type has changed since initialisation, or detected wrong,
31	Channel 3 type	or not same as first actuator.
32	Channel 4 type	
33	Channel 5 type	
34	Channel 6 type	
35	Channel 1 pulse	Too many pulse errors.
36	Channel 2 pulse	7
37	Channel 3 pulse	7
38	Channel 4 pulse	
39	Channel 5 pulse	
40	Channel 6 pulse	
41	Channel 1 Overload up	Overload occur outwards
42	Channel 2 Overload up	
43	Channel 3 Overload up	
44	Channel 4 Overload up	
45	Channel 5 Overload up	7
46	Channel 6 Overload up]
47	Channel 1 Overload down	Overload occur inwards
48	Channel 2 Overload down	
49	Channel 3 Overload down	7
50	Channel 4 Overload down	7
51	Channel 5 Overload down	
52	Channel 6 Overload down	

	Channel 1 Anti-	Anti-collision limit has been exceeded
	collision	
	Channel 2 Anti-	
	collision	
	Channel 3 Anti-	
	collision	
	Channel 4 Anti-	
	collision	
	Channel 5 Anti-	
	collision	
	Channel 6 Anti- collision	
	Channel 1 SLS	SIS input has been activated
	activation	SLS input has been activated
	Channel 2 SLS	
	activation	
	Channel 3 SLS	
	activation	
	Channel 4 SLS	
	activation	
	Channel 5 SLS	
	activation	
64	Channel 6 SLS	
	activation	
65	Channel 1B type	Type of port B of channel has been changed
66	Channel 2B type	
67	Channel 3B type	
68	Channel 4B type	
69	Channel 5B type	
	Channel 6B type	
	Channel 1A shorted	Short circuit detected on output
	Channel 1B shorted	
	Channel 2A shorted	
	Channel 2B shorted	
	Channel 3A shorted	
	Channel 3B shorted	
	Channel 4A shorted	
	Channel 4B shorted	
	Channel 5A shorted	
	Channel 5B shorted	
	Channel 6A shorted	
	Channel 6B shorted	
	Massage	Massage unit has been disconnected or failed
	DC-out	DC unit has been disconnected or failed
	Radio dead	Radio circuit has died and has had to be restarted
	Master	Connection to master lost OR following messages are from master
	Slave 1	Connection to 1st slave lost OR following messages are from 1st slave
	Slave 2	Connection to 2 nd slave lost OR following messages are from 2 nd slave
89	Slave 3	Connection to 3 rd slave lost OR following messages are from 3 rd slave

100	Forced initialisation	Forced initialisation initiated
	reference 1	Note: is not transmitted in LIN bus
101	Forced initialisation	
	reference 2	
102	Forced initialisation	
	reference 3	
103	Forced initialisation	
	reference 4	
104	Forced initialisation	
	reference 5	
105	Forced initialisation	
	reference 6	
106	Forced initialisation	
	reference 7	
107	Forced initialisation	
	reference 8	

For any further questions or concerns, please contact the LINAK Technical Department on 03 8796 9777 or your local sales representative.

MORE USEFUL RESOURCES

How to Sync your RF Controller

Activating the learning mode:

Activate the reset key on the RFR by using a pen or similar to keep the button pressed.



- Keeping the reset key activated; the RF handset must be activated by pressing a random key on the RF handset. The RF handset IDs are stored in the memory and at the same time, previous RF handset IDs are erased.
- After having activated the RF handset keys the reset key must be released.
- If no RF handset keys are activated during the matching procedure; no changes are made in the ID memory.
- Please be aware that other equipments (as e.g. doorbells), which use the 433 MHz can disturb the RF signal.

Every RF handset has its own 32 bit unique address and the RF protocol contains a check sum which ensures that only the handset that has been activated during the learning process can activate the system. No noise signal from other RF equipment can activate the system, but might prevent it from running depending on the signal strength of the noise signal.

The operation range for the HB10 is approx. 6 m, but depending on the surroundings where it is mounted it can be less. E.g. if the receiver is mounted in a cabinet along with other equipment.

The RF uses the frequency 433 MHz

Scan to download Desk Control App



Scan to set DPF
Desk Control Panels



Scan to initialize desk

